# 3M<sup>TM</sup> Splice Kit 5551-3/C-AC

5/8kV, 3-Conductor Splice Cable

For Splicing Shielded to Shielded Cable, or Shielded to Non-shielded Cable

# Instructions

#### IEEE Std. No. 404

5kV Class, 75kV BIL 8kV Class, 95kV BIL

#### **Kit Contents:**


- 6 Copper Tape Strips
- 3 Scotch<sup>®</sup> Electrode Wraps 13
- 5 Rolls of Scotch<sup>®</sup> Rubber Mastic Tape 2228 (3-1" wide, 2-2" wide)
- 3 Cold Shrink Insulators
- 3 Rolls of Scotch® Electrical Semi-Conducting Tape 13
- 3 Rolls of Scotch<sup>®</sup> Linerless Rubber Splicing Tape 130C
- 3 Shielding Braid Sleeves
- 6 Small Constant Force Springs
- 1 Scotch® Electrical Grounding Braid 25
- 2 Large Constant Force Springs
- 1 Roll of Scotch® Vinyl Electrical Tape 33
- 1 3M<sup>™</sup> Cleaning Kit CC-3 (3 cleaning pads)
- 1 Cold Shrink Jacket
- 2 15' Rolls of 3M<sup>™</sup> Armorcast Structural Material 4560-15 (For Armored Cables)
- 1 Instruction Sheet

#### **Kit Selection Chart**

NOTE: Final Determination Factor is cable insulation diameter.

	Kit Number	Primary Insulation O.D. Range	Conductor Size Range O.D.	
			Copper	Aluminum
	5551-3/C-AC	0.37"–0.78" (9,4–19,8 mm)	6—4/0	6–3/0

Table 1






Components Needed: (not supplied in the standard kit)

Connectors (for primary conductors) Ground Connectors (to connector ground wires)

## **1.0** Prepare Cables

- 1.1 Clean cable jackets by wiping with a clean, dry cloth for approximately 3 feet (1 meter) at each end.
- 1.2 Prepare cables using standard procedures, following the section below for each type of cable being used. Insulation removal distance is one-half the connector length.



Note: Copper tape strips are provided to secure the ends of the metallic shields.

Figure 1

- 1.3 For Wire Shielded Cables:
  - a. Remove cable jacket/armor as shown in (*Figure 1*).
  - b. Wrap 2 full wraps Scotch<sup>®</sup> Electrical Semi-Conducting Tape 13 over ground wires 5 1/2" (140 mm) from cable end (*Figure 2*).
  - c. Cut off ground wires to a length of 1 1/2" (38 mm) and fold back onto cable (*Figure 2*). Secure the ends with copper tape, if needed.
  - d. Remove cable semi-con as shown in (*Figure 2*).
  - e. Remove cable insulation from cable ends for a distance of 1/2 connector length (*Figure 2*).




Figure 2

- 1.4 For UniShield<sup>®</sup> Cables
  - a. Remove cable jacket/armor as shown in (*Figure 1*).
  - b. Wrap a vinyl tape band around cable jacket at a point 5 1/2" (140 mm) from cable end and remove drain wires from semi-con jacket to the leading edge of applied vinyl tape band (*Figure 3*).




Figure 3

- c. Cut off shield drain wires to a length of 1 1/2" (38 mm) and fold back onto cable (*Figure 4*).
- d. Install hose clamp as shown in (*Figure 4*). On the side of the clamp closest to the cable end cur 80% through cable jacket.
- e. Remove jacket by pulling against hose clamp. **Do not bell semi-con jacket** (*Figure 4*). *NOTE: Jacket may separate into two layers. Remove both layers of black semi-con jacket.*
- f. Remove hose clamp.
- g. Remove cable insulation from cable ends for a distance of 1/2 connector length (*Figure 4*).




Figure 4

### 2.0 Splicing Shielded to Shielded Cable

2.1 Slide cold shrink insulation tubes onto Cable Y, one per conductor, loose core ends first, until the cable semicon is visible (*Figure 5*).

NOTE: It may be necessary to unwind some of the excess core prior to putting on the cable. Do not unwind closer than 1/4" (6 mm) from insulation rubber.




Figure 5

4