Evolution™ Horizontal Cable Managers

Tools Required

#2 Phillips screwdriver

Parts List

Horizontal Panel
Horizontal Cover
(Rack mounting screws are not included)

Application

Rack-mount cable manager organizes patch cords and cables above and below patch panels and network switches.

Installation Notes

- Installation requires four equipment mounting screws, included with the rack or ordered separately.
- The cover will open up or down and can be removed when cabling.

Assembly Sequence

1. Remove the Horizontal Cover from the Horizontal Panel. The cover snaps onto the ends of the plastic, T-shaped cable guides (fingers).
2. Align the Horizontal Panel with the desired RMU spaces on the rack. The mounting holes at the back of the panel will align with rack-mount holes on the rack.
3. Install the panel with four equipment mounting screws using a #2 Phillips screwdriver.
4. Reattach the Horizontal Cover.
5. Dress cables into the manager using the fingers to organize cables.