# PHYSICAL INFRASTRUCTURE SYSTEMS

## Field Polish Fiber Optic Termination Kits

- For termination of all Panduit field polish connectors
- Fast acting adhesive; no long curing epoxy required for termination
- Kit provides consumables for terminating up to 200 field polish connectors
- Include installation instructions and stripping templates for all Panduit field polish connectors; also available on www.panduit.com



**FIELDKIT**

| Part Number | Part Description | Std. Pkg. Qty. |
|---|---|---|
| **Field Polish Termination Kits** | | |
| **FIELDKIT** | Tools, consumables, installation instructions and stripping templates necessary for termination of all Panduit field polish connectors; includes FHSCT heat shrink curing tool – 110VAC, 60Hz. | 1 |
| **FIELDKIT-G** | Tools, consumables, installation instructions and stripping templates necessary for termination of all Panduit field polish connectors; includes FHSCT-W heat shrink curing tool – 230VAC, 50Hz. | 1 |
| **Field Polish Consumables Refurbishment Kit** | | |
| **FIELDKITRFB** | Replenishes the field polish consumables required for termination of all field polish connectors; includes all of the same consumable items as the FIELDKIT or FIELDKIT-G field polish termination kit. | 1 |
| **Cleaning Consumables Kit** | | |
| **FCLEANKIT** | Replenishes the cleaning consumables required for termination of all fiber optic connectors; includes all of the same cleaning consumable items that are included in all Panduit termination kits. | 1 |
| **OptiCam® Kit Upgrade for Field Polish Connector Termination** | | |
| **FCAMKITUPG** | Upgrades FCAMKIT with the additional tools, consumables, installation instructions and stripping templates required for termination of all Panduit field polish connectors; includes FHSCT heat shrink curing tool – 110VAC, 60Hz. | 1 |
| **FCAMKITUPG-G** | Upgrades FCAMKIT with the additional tools, consumables, installation instructions and stripping templates required for termination of all Panduit field polish connectors; includes FHSCT-W heat shrink curing tool – 230VAC, 50Hz. | 1 |

For OptiCam® Pre-Polished Cam Termination Kits, see page C.101 of SA-NCCB51.
OptiCam® OCTT is a CLASS 1M LASER PRODUCT

A.
System
Overview

B.
Copper
Systems

C.
Fiber
Optic
Systems

D.
Power
over
Ethernet

E.
Zone
Cabling

F.
Wireless

G.
Outlets

H.
Media
Distribution

I.
Physical
Infrastructure
Management

J.
Overhead &
Underfloor
Routing

K.
Surface
Raceway

L.
Cabinets,
Racks &
Cable
Management

M.
Grounding &
Bonding

N.
Industrial

O.
Labeling &
Identification

P.
Cable
Management
Accessories

Q.
Index

**PANDUIT**® *PHYSICAL INFRASTRUCTURE SYSTEMS*

# Components for Field Polish Fiber Optic Termination Kits

| Part Number | Part Description | Std. Pkg. Qty. | Std. Ctn. Qty. |
|---|---|---|---|
| **Tools (included in FIELDKIT and FIELDKIT-G)** | | | |
| **FKITCASE** | Case for fiber termination kits. | 1 | — |
| **CST115** | Fiber cable jacket stripper. | 1 | — |
| **FALC** | Alcohol bottle (empty). | 1 | 10 |
| **FBFSP** | Fiber buffer stripper. | 1 | 10 |
| **FSCDVR** | Screwdriver. | 1 | 50 |
| **FGLS** | Safety glasses. | 1 | 10 |
| **FTWZR** | Tweezers. | 1 | 10 |
| **FWBTL** | Water bottle (empty). | 1 | 10 |
| **FKS** | Fiber Kevlar shears. | 1 | 10 |
| **FWRKMAT** | Fiber safe workmat. | 1 | 10 |
| **Tools (included in FIELDKIT, FIELDKIT-G, FCAMKITUPG and FCAMKITUPG-G)** | | | |
| **FSCRIBE** | Carbide scribe. | 1 | 10 |
| **FLCASCP** | 1.25mm adapter for FSCOPE. | 1 | — |
| **FLOUPEX10** | Eye loupe (10x). | 1 | — |
| **FCRP5** | Crimp tool (hex sizes: 0.048", 0.100", 0.128", 0.151", 0.190"). | 1 | — |
| **FLPT** | Crimp tool required for 1.6mm/2.0mm jacketed cable termination. | 1 | — |
| **FJPKGU** | Universal polishing puck (2.5mm ferrule). | 1 | 10 |
| **FLCPK** | LC polishing puck (1.25mm ferrule). | 1 | — |
| **FPAD** | Fiber polishing pad (70 durometer). | 1 | 10 |
| **FLCPAD** | Polishing pad and plate (85 durometer). | 1 | 10 |
| **FHSCT** | Heat shrink curing tool (110VAC, 60Hz) required for 1.6mm/2.0mm jacketed cable termination (included in FIELDKIT and FCAMKITUPG). | 1 | — |
| **FHSCT-W** | Heat shrink curing tool (230VAC, 50Hz) required for 1.6mm/2.0mm jacketed cable termination (included in FIELDKIT-G and FCAMKITUPG-G). | 1 | — |
| **Field Polish Consumables (included in FIELDKIT, FIELDKIT-G, FIELDKITRFB, FCAMKITUPG and FCAMKITUPG-G)** | | | |
| **FSYR-X** | Syringes with needle tips. | 10 | 50 |
| **FPWIRE** | Piano wire. | 1 | 10 |
| **LJSL4-Y3-2.5** | Cable labels. | 1 | 10 |
| **FJPMR** | Primer (50ml). | 1 | 10 |
| **FJPXY** | Anaerobic adhesive (10ml). | 1 | 10 |
| **FPP5-L** | 5µm polishing paper ($AL_2O_3$). | 50 | 250 |
| **FPF1-V** | 1µm diamond polishing film. | 5 | 50 |
| **FLCFPLF-X** | 0.05µm lapping film. | 10 | — |
| **Cleaning Consumables (included in FIELDKIT, FIELDKIT-G, FIELDKITRFB and FCLEANKIT)** | | | |
| **FWP-C** | Lint-free wipes. | 100 | 1000 |
| **FSWB-C** | Cleaning swabs. | 100 | 1000 |
| **FSTY** | Safety stickers for fiber scraps. | 1 | 10 |
| **PFX-0** | Permanent marking pen – fine tip (one included in each kit). | 12 | 144 |
| **Replacement Parts** | | | |
| **FSCRBLD** | Replacement blade for carbide scribe. | 1 | 10 |

Order number of pieces required, in multiples of Standard Package Quantity.  Prime items appear in **BOLD**.