

General Instructions

1. Storage ▶
2. Durability ▶
3. FEPA-Safety-Recommendations ▶



1. Storage of Abrasives

VSM-storage regulations of Abrasives:

- room temperature 18 - 22°C
- relative humidity 55 - 65 %
- VSM-abrasives should never be stored next to windows, doors, heat sources, damp walls or floors. Exposure to sun has to be avoided.
- store in open shelves, if possible in original packaging.
- VSM-wide belts should be taken out of packaging 12 - 24 hours before usage. For acclimatisation they have to be kept close to the grinding machine without kinks on large dimensioned rolls (cylinders).



2. Durability of VSM-Abrasives

VSM-abrasives are produced on modern manufacturing plants in carefully controlled processes. Planning and control of the processes are supervised by an up-to-date quality management system DIN/EN/ISO 9001.

Thereby they achieve their high quality and performance.

This high quality and performance stays preserved for 5-10 years, if the VSM-Abrasives are stored correctly, i. e., in accordance with the VSM-recommendations.

3. FEPA-Safety Recommendations

The leaflet with detailed FEPA-Safety recommendations must be handed to all users.



FEPA SAFETY RECOMMENDATIONS FOR THE USE OF ABRASIVE PRODUCTS

PASS ON THIS LEAFLET TO THOSE USING THE ABRASIVE PRODUCT

The recommendations contained in this leaflet should be followed by all users of abrasive products in the interests of their personal safety

	Not permitted for hand-held or manually-guided grinding	-	Only permitted for use on totally enclosed machines
	Not permitted for wet grinding		Read the instructions
	Not permitted for face grinding		Wear eye protection
	Do not use if damaged		Wear hearing protection
	Only permitted with a back-up pad		Wear gloves
-	Only permitted for wet cutting		Wear a respirator