



CS510



CS520



CS530



CS540

Spares and Replacement Parts

83323-12	83322-12	82905-12
86179-02	86180-01	64399-03
84604-01	84605-01 87229-01 (Ear cushions only, qty 2)	84606-01
39954-01	84123-01	38338-25 (Qty 25)
80287-01	60961-35	66935-05

Part No.	Description
83323-12	Spare (CS510)
83322-12	Spare (CS520)
82905-12	Spare (CS530)
86179-02	Spare (CS540)
86180-01	Spare Battery (CS540)
64399-03	Headset Battery (with Removal Tool, CS510 / CS520)
84604-01	Spare Fit Kit, Earloops / Earbuds (CS540)
84605-01	Spare Headband Over-The-Head (CS540)
87229-01	Spare Leatherette Ear Cushions (Qty 2, W440)
84606-01	Spare Headband Behind-The-Head (CS540)
86009-01	Spare Telephone Interface Cable (Savi and CS500) (not shown)
39954-01	T-piece Adapter (Training Lead for Wireless Systems)
81423-01	Spare Universal AC Power Adapter (CS500)
38338-25	Ear Cushions, Leatherette (Qty 25, CS510 / CS520)
80287-01	Spare, OLI, Straight Plug
60961-35	HL10 Lifter, Straight Plug
66935-05	Replacement Ear Tips (CS530) (5,3 with Gel Tips)
88940-01	Spare Ear Tip, Small (Qty 25, CS540) (not shown)
88941-01	Spare Ear Tip, Medium (Qty 25, CS540) (not shown)

EHS

37818-11	38908-11	37820-11
38350-11	38439-11	38734-11
38633-11	83018-11	87317-01

Part No.	Description
37818-11	<b>APS-11</b> Siemens / Funkwerk
38908-11	<b>APA-23</b> Alcatel
37820-11	<b>APT-31</b> Avaya (Tenovis)
38350-11	<b>APC-41</b> Cisco
38439-11	<b>APP-51</b> Polycom
38734-11	<b>APV-63</b> Avaya
38633-11	<b>APV-66</b> Avaya (EU-24 Interface)
83018-11	<b>APV-71</b> Cisco / Nortel USB
87317-01	<b>APC-45</b> Cisco