



Fluke OC4USB USB Interface Cable



Overview:

Safety-designed interface cable to connect the optically-isolated serial interface port of Scopemeter or Power Quality Analyzer to a standard USB-interface on your PC. Optical isolation allows you to float your instrument at mains voltages or beyond, while being connected to your PC.

Features:

- Supports the Fluke 120 Series and Fluke 190 Series ScopeMeters, as well as the 43, 43B and 430 Series [Power Quality analyzers](#)
- Supports Windows Vista/XP/2000/Me/98 SE
- Cable length 1.5 m (4.9 ft)

| Model Name | Description |
|--------------|----------------------------------|
| Fluke OC4USB | Fluke OC4USB USB Interface Cable |