DOOR LOCKS

			Uncoded service pack no alarm, non lighted chrome	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105	
Buick	Electra	1977-88	Uncoded service pack no alarm, non lighted black	DL1525U	Coded pair	DL1525	Use face cap RP6520 (P-41-202) Use tumbler series P-41-101/105	
			Coded pair with factory alarm no lighted keyhole	DP-41-115	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105			
			With lighted keyhole – replacement locks available from Strattec					
Buick	Enclave	2008	Uncoded service pack	D-41-003	Use tumbler series P-41-0 tumblers may be used for GM dealers or originally in	locks not sold	d by ASP including some locks sold by	
Buick	Estate Wagon	All	see Le Sabre					
Buick	Le Sabre	1968-70	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105	
Buick	Le Sabre 2-door	1971	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105	
Buick	Le Sabre 4-door	1971	Uncoded service pack	DL1582U	Coded pair	DL1582	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105	
Buick	Le Sabre	1972-76	Uncoded service pack	DL1582U	Coded pair	DL1582	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105	
			Uncoded service pack no alarm, non lighted	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105	
		1977-99	Coded pair with factory alarm no lighted keyhole	DP-41-115	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105			
Buick	Le Sabre		Uncoded service pack with factory alarm no lighted keyhole	D-41-215	NOTE: D-41-215 uses H keyway used on 1977, 1981, and 1991-99 models only. Uncoded service package not available with other keyways as used 1978-80 and 1982-90. Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105			
			With lighted keyhole – re	placement loc	ks available from Strattec			
Buick	Le Sabre	2000-05	Uncoded service pack	D-41-001			-41-001 sold by ASP. Different tumblers including some locks sold by GM	
Buick	Lucerne	2006-07	Replacement locks avail	able from Stra				
Buick	Opel (Japan)	1976-79	Uncoded service pack	D-24-201	Use face cap P-24-203 (chrome) or P-24-204 (black) Use tumbler series P-30-141/144			
			Uncoded service pack no alarm, non lighted	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105	
Buick		1989-96	Coded pair with factory alarm no lighted keyhole	DP-41-115 Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105				
	Park Avenue		Uncoded service pack with factory alarm no lighted keyhole D-41-215 D-41-215 D-41-215 D-41-215 Uncoded service package not available with other keyways as used 1989-90 Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105					
			With lighted keyhole – replacement locks available from Strattec					
Buick	Park Avenue	1997-05	Replacement locks available from Buick / GM dealers only. Parts to service original locks are available as follows: Face cap: P-41-203, Dust cover assembly: P-41-233 Plastic pawls (1997-99 only): P-41-301 for right side, P-41-302 for left side Use tumbler series P-41-111/114					
			Uncoded service pack no alarm, non lighted	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105	
Buick	D W.	1988-92	Coded pair with factory alarm no lighted keyhole	DP-41-115	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105			
	Reatta		Uncoded service pack with factory alarm no lighted keyhole	D-41-215	NOTE: D-41-215 uses H keyway used on 1991-92 models only. Uncoded service package not available with other keyways as used 1988-90 Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105			
			With lighted keyhole – replacement locks available from Strattec					
Buick	Regal	1973-78	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105	
Buick	Pagel 2 dese	1979-87	Uncoded service pack (chrome)	DL1582U	Coded pair (chrome)	DL1582	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105	
	Regal 2-door		Uncoded service pack (black)	DL1527U	Coded pair (black)	DL1527	Use face cap RP6520 (P-41-202) Use tumbler series P-41-101/105	
Buick	Regal 2-door	1988-97	Uncoded service pack	DL1508U	Coded pair	DL1508	Use tumbler series P-41-101/105	
Duiok	Regal 4-door	1973-87	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105	
Buick								
Buick	Regal 4-door	1988-97	Uncoded service pack chrome Uncoded service pack	DL1580U	Coded pair chrome	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105 Use face cap RP6520 (P-41-202)	

DOOR LOCKS

Plymouth	Neon (PL)	1994-05	Uncoded service pack	DL6847U	Coded pair	DL6847	Use face cap RP6215 (P-44-203) Use tumbler series P-44-111/114
Tymoun	140011 (1 2)	1004-00	NOTE: For 1994 Neon t	he lock origina	ally installed on the car whe	n it was new r	may use tumbler series P-44-101/104
Plymouth	Prowler	1998-02	Uncoded service pack	D-44-019	Use face cap RP6215 (P-44-203) Use tumbler series P-44-111/114		
Plymouth	Sapporo (import)	1978-83	Coded lock without pawl	D-22-106	If original pawl cannot be Use face cap P-30-201 Use tumbler series P-30-1		wl P-30-301, reversible RH & LH
Plymouth	Sundance (P)	1990-92	Uncoded service pack chrome	DL4816U	Coded pair chrome	DL4816	Use face cap RP6215 (P-44-203) Use tumbler series P-44-101/104
	Suridance (F)		Uncoded service pack black	DL4822U	Coded pair black	DL4822	Use face cap RP6220 (P-44-204) Use tumbler series P-44-101/104
Plymouth	Sundance (P)	1993-94	Uncoded service pack chrome	DL4817U	Coded pair chrome	DL4817	Use face cap RP6215 (P-44-203) Use tumbler series P-44-101/104
			Uncoded service pack black	DL4823U	Coded pair black	DL4823	Use face cap RP6220 (P-44-204) Use tumbler series P-44-101/104
Plymouth	Voyager	1990	Uncoded lock with pawl reversible R&L	DL1502U	Coded pair with pawls	DL1502	Use tumbler series P-44-121/126
Plymouth	Voyager	1991	Uncoded service pack	DL4815U	Coded pair	DL4815	Use face cap RP6218 (P-44-201) Use tumbler series P-44-101/104
Plymouth	Voyager	1992	Uncoded service pack	DL4816U	Coded pair	DL4816	Use face cap RP6215 (P-44-203) Use tumbler series P-44-101/104
Plymouth	Voyager	1993-94	Uncoded service pack	DL4817U	Coded pair	DL4817	Use face cap RP6215 (P-44-203) Use tumbler series P-44-101/104
Plymouth	Voyager	1995	Uncoded service pack	DL6847U	Coded pair	DL6847	Use face cap RP6215 (P-44-203) Use tumbler series P-44-111/114
Plymouth	Voyager	1996-00	Uncoded service pack	D-44-019	Use face cap RP6215 (P- Use tumbler series P-44-1		
Plymouth	Voyager	2001-02	Uncoded service pack	DL6847U	Coded pair	DL6847	Use face cap RP6215 (P-44-203) Use tumbler series P-44-111/114
Pontiac	1000	1981-87	see T1000				
Dontino	6000	1002.01	Uncoded service pack (chrome)	DL1580U	Coded pair (chrome)	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Pontiac	8000	1983-91	Uncoded service pack (black)	DL1525U	Coded pair (black)	DL1525	Use face cap RP6520 (P-41-202) Use tumbler series P-41-101/105
Pontiac	Acadian	1975-87	see T1000				
Pontiac	Astre	1971-77	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Pontiac	Aztek	2001-05	Replacement locks available from Pontiac / GM dealers only. Face cap must be removed to service original lock on the car, replacement caps not currently available Use tumbler series P-41-111/114				
Pontiac	Bonneville	1967-70	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Pontiac	Bonneville	1971-76	Uncoded service pack	DL1582U	Coded pair	DL1582	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
			Uncoded service pack no alarm, non lighted chrome	DL1580U	Coded pair no alarm, non lighted chrome	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Pontiac	Bonneville	1977-91	Uncoded service pack no alarm, non lighted black	DL1525U	Coded pair no alarm, non lighted black	DL1525	Use face cap RP6520 (P-41-202) Use tumbler series P-41-101/105
			Uncoded service pack with factory alarm no lighted keyhole chrome	D-41-215	Uncoded service pack with factory alarm no lighted keyhole black	D-41-242	NOTE: D-41-215 and D-41-242 use H keyway used 1991 only. Uncoded service package not available with other keyways as used 1977-90 Use face cap RP6520 (P-41-202) Use tumbler series P-41-101/105
			Coded pair with factory alarm no lighted keyhole chrome	DP-41-115	Use chrome face cap RP6036 (P-41-201) Use black face cap RP6520 (P-41-202) Use tumbler series P-41-101/105		
			, ,	hole – replacement locks available from Strattec			
Pontiac	Bonneville	1992-99	Uncoded service pack RH no alarm	D-41-243	Uncoded service pack LH no alarm	D-41-244	Use tumbler series P-41-101/105
			Uncoded service pack RH with alarm	D-41-245	Uncoded service pack LH with alarm	D-41-246	Use tumbler series P-41-101/105
Pontiac	Bonneville	2000-05	Uncoded service pack	D-41-002		sold by ASP i	41-002 sold by ASP. Different tumblers including some locks sold by GM dealers was new
Pontiac	Catalina	1967-81	see Bonneville	I	i singilising motanou off th		>
Pontiac	Executive	1967-81	see Bonneville				
	Fiero	1984-89	Replacement locks availa		tec		
Pontiac	FIEIO	1904-89	Use tumbler series P-41- Uncoded service pack	101/105 DL1580U	Coded pair (abrama)	DL1580	Use face cap RP6036 (P-41-201)
Pontiac	Firebird	1967-92	(chrome) Uncoded service pack		Coded pair (chrome)		Use tumbler series P-41-101/105 Use face cap RP6520 (P-41-202)
			(black)	DL1525U	Coded pair (black)	DL1525	Use tumbler series P-41-101/105

ASP PART NUMBERING SYSTEM

The ASP Part Numbering System

Working with the ASP part numbers is easier if you have a basic understanding of the part numbering system, explained here:

The first letter or letters of the part number identify what type of product the part number is:

Α	Keying kits and parts assortments
В	Luggage compartment locks
С	Ignition locks
D	Door locks (including complete locks that include the door handle)
DH	Door handles (except complete locks that
	include the door handle)
DP	Door locks (keyed alike pair)
Ε	Engine compartment locks
F	Fasteners (including lock retaining clips,
	shear-head bolts, door panel fasteners, etc.)
G	Glove compartment and stowage locks
KB	Key blanks
Р	Lock service parts (including tumblers, face
	caps, and other parts)
RK	Remote head key blanks
S	Lock sets
Т	Fuel tank locks
W	Ignition switches (wiring assembly only without

The second two digits of the part number tell you the PRIMARY brand of vehicle that the item is used on:

lock cylinder)

00	Various cars
11	Alfa Romeo
12	Audi
13	BMW
14	British Cars (Austin, Jaguar, Land Rover, MG,
17	Range Rover, Triumph)
15	British Chrysler (Plymouth Cricket, Sunbeam,
	Hillman)
16	Nissan / Datsun / Infiniti
17	Fiat
18	European Ford (Capri, Fiesta, Merkur)
19	Honda / Acura
20	Mazda
21	Mercedes-Benz
22	Mitsubishi
23	GM Europe (Cadillac Catera, Pontiac Lemans,
	Opel)

24 Isuzu (including General Motors brands) 25 Peugeot 26 Porsche Renault 27 28 Saab 29 Subaru 30 Toyota / Lexus / Scion / Hino truck 31 Volkswagen 32 Volvo 33 Suzuki 34 Lada 35 Lancia 36 Hyundai 37 Daihatsu 38 Citroen 39 Yugo Kia 40 41 General Motors USA (Buick, Cadillac, Chevrolet, GMC, Oldsmobile, Pontiac) 42 Ford / Lincoln / Mercury (USA) American Motors (including some Heavy Trucks 43 and Jeep) 44 Chrysler / Dodge / Jeep / Plymouth 45 Skoda 49 Saturn 50 Daewoo (including Chevrolet Aveo, Saturn Vue, other General Motors brands) 55 Renault truck (including some Mack trucks) 56 Freightliner truck 57 Kenworth truck 93 Harley Davidson Motorcycle 94 Honda Motorcycle

For example, if you have part number C-30-107, by understanding the part numbering system you will know that the part is an ignition lock (first letter C), which fits a Toyota (second two digits 30).

Yamaha Motorcycle

98

There are exceptions to this system created by the same part being used on more than one brand of car. Also some parts are used in more than one place on the car – for example, B-14-210 is numbered as a luggage compartment lock, but also is used as an ignition lock or door lock on some cars.

ASP PART NUMBERING SYSTEM

The same part being used on more than one brand of car is explained by lock families, as follows:

Audi - also found on some Porsche and Volkswagen

Ford USA – also found on some Mazda and Nissan

Honda / Acura - also found on some Isuzu

Mazda – also found on some Chrysler imports, Ford imports, General Motors imports, GEO, Mitsubishi, Suzuki

Nissan - also found on some Subaru and Isuzu truck

Toyota – also found on some Chrysler imports, Daihatsu, General Motors imports, GEO, Hyundai, Isuzu, Kia, Mazda, Mitsubishi, Suzuki.

Volkswagen - also found on some Audi and Porsche (tumblers also used on BMW)

You will also find some parts that are used among the brands of the following groups of cars:

British cars - Aston Martin, Austin, English Ford, Jaguar, Jensen, Land Rover, MG, Morgan, Range Rover, Rover car, Sterling car, Triumph, TVR, Volvo.

French cars - Peugeot, Renault, Citroen

German cars - Audi, BMW, Daewoo, General Motors (Cadillac Catera, Chevrolet Aveo, Pontiac Lemans, others), Mini, Porsche, Mercedes-Benz, Volkswagen

Italian cars - Alfa Romeo, Bertone, Ferrari, Fiat, Iveco, Lada, Lamborghini, Lancia, Maserati, Pininfarina, Yugo

Lockcraft Part Numbers

The first two letters of the part number identify what type of product the part number is:

DL Door lock LC Ignition lock LS Lock set

RP Lock service parts (including tumblers, face caps, and other parts)

SK Keying kits and parts assortments
TL Luggage compartment locks

Lockcraft part numbers that end in "U" are uncoded locks.

There have been many changes to the Lockcraft part numbers over the past years, explained as follows:

Most old Lockcraft part numbers had no letter prefix. For example, old part number 1426 was changed to LC1426 to identify the type of product.

Some old Lockcraft part numbers had a letter prefix "A", which was changed to "RP". For example, part number A6001 was changed to RP6001. This could be confusing if you have an old Lockcraft or All Lock keying kit or parts assortment which identified the parts inside by the letter prefix "A". When reordering simply change the "A" to "RP".

Some old Lockcraft part numbers had a digit "3" at the end of the part number, which designated poly bag packaging. For example, part number LC14263 designated the LC1426 ignition lock in a poly bag. The currently used part numbers now eliminate the "3" at the end and using the example LC14263 is now simply LC1426.

Some old Lockcraft part numbers had a digit "8" at the end of the part number, which designated that it was an uncoded lock. For example, part number LC14268 designated the LC1426 ignition lock in uncoded form. The currently used part numbers now use "U" at the end of the part number instead of the "8". Using the example LC14268 is now LC1426U.

PART NUMBER LISTING and POPULARITY RATINGS

Part Number Listings and Popularity Ratings

Pages 214-233 contain a complete listing of ASP part numbers, with the 2008 popularity rating for each part number. The popularity ratings are explained as follows:

- A = Most popular items (lock cylinders and replacement parts)
- **B** = Second most popular group of lock cylinders
- Y = Replacement parts (keying kit refill tumblers, face caps, etc.), popularity equivalent to B-rated lock cylinders
- **C** = Third most popular group of lock cylinders
- Z = Replacement parts (keying kit refill tumblers, face caps, etc.), popularity equivalent to C-rated lock cylinders
- **H** = Items not recommended for stock by distributors, these parts are normal stock items for the ASP warehouse and available for drop shipments (HI-SPEED delivery). Orders must be placed through your distributor, and are subject to stock on hand at ASP. Some distributors may have selected H-rated items in stock.
- **S** = Special order items only, may not be in stock at ASP. These items may be subject to minimum order quantities if needed. Some distributors may have selected S-rated items in stock.
- **DWO** = Discontinued when out. Some items may still have limited stock at ASP or at some distributors, but will not be restocked when existing supplies are sold out.

ASP products are sold through the network of locksmith supply distributors located throughout the USA and Canada.

With over 4,000 different part numbers in our range, it is impossible and impractical for distributors to keep every part number in stock. Thus we have assigned each of our part numbers a popularity rating to assist distributors in keeping stock. We have implemented new distributor stocking programs based on these popularity ratings. Please check www.carlocks.com for the most current information about our distributor stocking guidelines. ASP is working closely with our distributors to provide you the fastest delivery possible at the lowest possible cost.

Distributors who make a commitment to keep stock according to our recommendations are listed on www.carlocks.com

This list is subject to change at any time. Distributors who do not keep the stocking commitment will be removed from the list.

Explanation of other notes on the part number listing

- a. Some items have (now use ...) to the right of the part number, with a rating of DWO. For example: A-13-105 (now use A-31-110) this means that A-13-105 has been superseded by A-31-110.
- b. Some items have (substitute ...) to the right of the part number, with a rating of DWO. For example: B-19-154 (substitute B-19-155) this means that you can substitute B-19-155 for B-19-154, but there is some difference between the two parts. A complete listing of these part numbers with a brief explanation of the difference between each superseded part and the replacement part is provided on pages 234-237.
- c. Some items have (see ...) to the right of the part number, with no popularity rating. For example: B-16-105 (see B-16-205), with no popularity rating. Then go to B-16-205 and you will see it listed as B-16-205 (B-16-105) with the popularity rating of B. This is a result of our consolidating some similar interchangeable part numbers. In this example, whether you order B-16-105 or B-16-205, you will get the same part at the same price. A complete listing of these part numbers is provided on pages 238-239.