

REAR COMPARTMENT LOCKS

BMW	5-series	1989-95	Complete lock except 1991-93 M3 sedan	B-13-330	Complete lock 1991-93 M3 sedan	B-13-331	Use tumbler series P-13-101/104 (P-21-111/114)
BMW	5-series	1989-95	Complete lock station wagon	B-13-335	Use tumbler series P-13-131/144		
BMW	5-series	1996-03	Complete lock	B-13-336	Use tumbler series P-13-131/144		
BMW	5-series	2004-07	Replacement locks available from BMW dealers only				
BMW	6-series	1977-86	Complete lock round lock body	B-13-314	Use tumbler series P-13-101/104 (P-21-111/114)		
BMW	6-series	2004-07	Replacement locks available from BMW dealers only				
BMW	7-series	1977-87	Complete lock	B-13-313	Use tumbler series P-13-101/104 (P-21-111/114)		
BMW	7-series	1988-94	Complete lock	B-13-332	Use tumbler series P-13-131/144		
BMW	7-series	1995-01	Complete lock	B-13-327	Use tumbler series P-13-131/144		
BMW	7-series	2002-08	Replacement locks available from BMW dealers only				
BMW	8-series	1991-98	Complete lock	B-13-333	Use tumbler series P-13-131/144		
BMW	Z3	1996-00	Complete lock coupe, roadster	B-13-334	Complete lock Hatchback	B-13-338	Use tumbler series P-13-131/144
Buick	Many Models	up to 66	Uncoded plug	B-41-303	Use tumbler series P-41-101/105		
Buick	Apollo	1973-75	Uncoded service pack	TL1575U	Coded lock	TL1575	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Buick	Centurion	1971-73	Uncoded service pack	TL1575U	Coded lock	TL1575	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
			NOTE: RP6036 (P-41-201) face cap cannot be used for the lock originally installed on the car on some 1971-73 models with emblem flap over the lock cylinder. Replace the complete lock using TL1575U or TL1575.				
Buick	Century except station wagon	1973-96	Uncoded service pack	TL1575U	Coded lock	TL1575	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Buick	Century wagon	1973-77	Uncoded service pack	TL1576U	Coded lock	TL1576	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Buick	Century wagon	1984-96	Replacement locks available from Strattec Use tumbler series P-41-101/105				
Buick	Century	1997-04	Replacement locks available from Strattec Use face cap RP6036 (P-41-201) Use tumbler series P-41-161/164				
Buick	Electra	1968	Uncoded service pack	TL1575U	Coded lock	TL1575	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Buick	Electra	1969-70	Uncoded service pack	TL1576U	Coded lock	TL1576	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Buick	Electra	1971	Uncoded plug	B-41-301	Use tumbler series P-41-101/105		
Buick	Electra	1972-88	Uncoded service pack	TL1575U	Coded lock	TL1575	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
			Uncoded service pack black	TL1523U	Coded lock black	TL1523	Use face cap RP6520 (P-41-202) Use tumbler series P-41-101/105
			NOTE: RP6036 (P-41-201) face cap cannot be used for the lock originally installed on the car on some 1972-76 models with emblem flap over the lock cylinder. Replace the complete lock using TL1575U or TL1575.				
Buick	Enclave	2008	Replacement locks available from Strattec				
Buick	Estate Wagon	1968-70	Uncoded service pack	DL1580U	Coded lock (available as a pair only)	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Buick	Estate Wagon	1971-76	Replacement locks available from Strattec Use tumbler series P-41-101/105				
Buick	Estate Wagon	1977-91	Uncoded service pack	DL1580U	Coded lock (available as a pair only)	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Buick	Le Sabre	1968-91	Uncoded service pack	TL1575U	Coded lock	TL1575	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
			NOTE: RP6036 (P-41-201) face cap cannot be used for the lock originally installed on the car on some 1971-76 models with emblem flap over the lock cylinder. Replace the complete lock using TL1575U or TL1575.				
Buick	Le Sabre	1992-94	Replacement locks available from Strattec Use tumbler series P-41-101/105				
Buick	Le Sabre	1995-99	Uncoded service pack	TL1575U	Coded lock	TL1575	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Buick	Le Sabre	2000-05	Uncoded service pack	B-41-001	Use tumbler series P-41-121/124		
Buick	Lucerne	2006-07	Replacement locks available from Strattec				
Buick	Opel (Japan)	1976-79	Complete lock	B-24-102	Use tumbler series P-30-141/144		
Buick	Park Avenue	1989-96	Uncoded service pack	TL1575U	Coded lock	TL1575	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Buick	Park Avenue	1997-05	Replacement locks available from Buick / GM dealers only. Use face cap RP6036 (P-41-201) Use tumbler series P-41-111/114				
Buick	Reatta	1988-92	Replacement locks available from Strattec Use tumbler series P-41-101/105				
Buick	Regal except station wagon	1973-97	Uncoded service pack chrome	TL1575U	Coded lock chrome	TL1575	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
			Uncoded service pack black	TL1523U	Coded lock black	TL1523	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Buick	Regal station wagon	1978-83	Replacement locks available from Strattec Use tumbler series P-41-101/105				