



### The quality, durability, and convenience you need

These lightweight, affordable insulation testers are perfect for troubleshooting, commissioning and preventive maintenance applications.

- Automatic calculation of polarization index and dialectric absorption ratio (1507 only)
- Multiple test voltages: 50 V, 100 V, 250 V, 500 V, 1000 V (1507 only)
- · Remote test probe for rapid testing
- Insulation test range 0.01 M $\Omega$  to 10 G $\Omega$  (1507), 0.1 M $\Omega$  to 2 G $\Omega$  (1503)
- Compare (Pass/Fail) function for repetitive tests (1507 only)
- Live circuit detection prevents insulation test if voltage > 30 V is detected
- Auto-discharge of capacitive voltage
- AC/DC voltage: 0.1 V to 600 V
- · Lo ohms/Earth-bond continuity (200 mA) for checking connections and motor windings
- Resistance: 0.01  $\Omega$  to 20.00  $k\Omega$



	1507	1503					
Insulation test voltages 50 V, 100 V, 250 V, 500 V, 1000 V	•						
Insulation test voltages 500 V, 1000 V		•					
Insulation resistance	0.01 MΩ to 10 GΩ	0.1 MΩ to 2 GΩ					
Auto-discharge of capacitive voltage	•	•					
Continuity function	200 mA acc. EN 61557-4						
Resistance	0.1 Ω to 20.00 kΩ	0.1 Ω to 20.00 kΩ					
Auto power off	•	•					
Warranty (years)	1	1					

#### Ordering information

Models	Included accessories
FLUKE-1507 Insulation Tester	Remote probe, silicone test leads, test probes, large alligator clips, holster, users manual
FLUKE-1503 Insulation Tester	Remote probe, silicone test leads, test probes, large alligator clips, holster, users manual















Magnetic Meter Hanger frees up both hands to focus on making measurements safely.

Check connections and motor windings with Lo ohms/earth-bond continuity test



#### **Recommended accessories**



Test Lead Set



Lead Set







### Fluke cases and holsters

A premium meter deserves a premium case

#### **Hard cases**

#### **CXT Series Extreme Cases**

- · Models CXT80, CXT170, and CXT280 for various meter compatibility
- · Unbreakable, watertight, airtight, chemical resistant and corrosion proof



 Dimensions (HxWxD): 30.5 x 36 x 10.5 cm (12 x 14.2 x 4.1 in)



 Dimensions (HxWxD): 39.7 x 34.6 x 12.2 cm (15.7 x 13.6 x 4.8 in)

### C1600 Gear Box

- · Includes five hook and loop straps to wrap cords and test leads
- Dimensions (HxWxD): 26 x 39 x 20 cm (10 x 15 x 7.8 in)

#### **CXT1000 Extreme Hard** Case - New

- · Rugged hard case that allows you to configure the diced foam interior and offers maximum protection
- Waterproof to a depth of 3 feet, airtight, and 0-ring sealed for automatic pressure equalization
- Dimensions (HxWxD): 34.3 x 46.5 x 17.8 cm (13.5 x 18.3 x 7 in)





FLUKE

## Leather cases

#### C520A Leather **Tester Case**

 Dimensions (HxWxD): 25.6 x 15.4 x 10.6 cm (10 x 6 x 4 in)

#### C510 Leather **Meter Case**

 Dimensions (HxWxD): 28.7 x 17.9 x 10.6 cm  $(11 \times 7 \times 4 \text{ in})$ 



#### **Holsters**

#### **H15 Electrical Tester Holster**

- · High quality 1000D fabric
- Dimensions (HxWxD): 27.9 x 9.2 x 5.1 cm (11 x  $3.6 \times 2 \text{ in}$

#### **H80M Protective** Holster

- Includes a hanging magnet, general purpose hanger, and hook and loop straps
- Dimensions (HxWxD): 19 x 9.5 x 4.3 cm (7.5 x 3.7 x 1.7 in)

#### **H5 Electrical Tester Holster**

• Dimensions (HxWxD): 19.2 x 9 x 3.8 cm (7.5 x 3.5 x 1.5 in)

#### **H3 Clamp Meter** Holster

• Dimensions (HxWxD): 23.1 x 9 x 6.4 cm (9 x  $3.5 \times 2.5 \text{ in}$ 

#### H6 IR **Thermometer** Holster

• Dimensions (HxWxD): 30.2 x 17.8 x 5.7 cm  $(11.9 \times 7 \times 2 \text{ in})$ 













# Fluke cases and holsters

A premium meter deserves a premium case

### Cases and holsters selection guide

cases and noisters selection guide																									
	113/114/115/116/117	27 11/28 П	77-4/175/177/179	83V/87V	233	287/289	8845A/8846A/8808A	120/190/22X Series	51-II/52-II/53-II B/54-II B	561/566/568	89/99/89	323/324/325	355	365/373/902	374 FC/375FC /376 FC/ 381	705/707	712/714/715/717/72X Series	718/719	753/754	787/789	T+/T+PRO	T5-600/T5-1000	1503/1507/1577/1587 FC		
C12A	•															•									
C23	•		•	•	•							•													
Camo-C25	•	•	•	•	•	•			•			•					•			•	•		•		
C25	•	•	•	•	•	•			•			•					•			•	•		•		
C33												•		•	•						•	•			
C35			•		•																•	•			
Camo-C37												•		365	•						•		•		
C43				•	•	•		•		•			•	•	•					•					
C50	•																				•				
C75					The C	75 is	desig	ned to	b hold	test	leads,	probe	es, cli	ps an	d othe	er req	required accessories								
C90	•		•						•												•				
C100		•	•	•						•			•				71X			787					
C101	•	•	•	•	•	•		•	•		•	•		•	•	•	•	•		•		•	•		
C115/C116	•	•	•	•	•	•		•						365			•	•		•			•		
C125		•	•	83V	•																				
C150												•		•	•						•	•			
C280	•	•	•	•	•	•		•	•							•	•	•		•	•				
C345				Th	e per	fect c	ase fo	r carr	ying	a wid	e ran	ge of I	Fluke	hand	held t	est to	ols an	id acc	essor	ies					
C510			•						•					•	•					787					
C520A																					•	•			
C550/C1600	The C550 and C1600 are large enough to hold accessories and multiple test									tools															
C781						•		•						•	•		72X	•	•	789			•		
C789								•		•			•	365				•		•					
C799																			•						
C800			•	•						•			•	•	•		71X			787					
CXT80		•		•	•												72X			•					
CXT170	•		•						•								71X			•			•		
CXT280						•														•					
CXT1000			The	CXT1	000 i	is des	igned	to sto	ore, ca	arry, a	nd pr	otect	a wid	le ran	ge of	Fluke	test t	ools a	and a	ccesso	ries				
H15																					•	•			



