


B



This diagram illustrates the step where the front panel is attached to the main unit. The front panel, which has a circular cutout and a handle, is shown being aligned with the main unit's frame. A screwdriver is used to secure the panel into place.

A

- # A

TITLE				
J-PRO J-HOOK WITH 360° HAMMER-ON BEAM CLAMP (JP75HBC__R-__)				
CUSTOMER DRAWING				
ITEM REVISION NAME				
12I031AI/00				
DATASET FILE NAME				
12I031AI_DC_C11008/00A				
UNLESS OTHERWISE SPECIFIED, DIMENSIONAL TOLERANCES ARE: IN [mm] .x : .1 [2.54] .xxx : .005 [.127] .xx : .01 [.25] ANGLES : 5 °			MATERIAL: SEE NOTE 2	
			DRAWING NUMBER: C11008	
DRAWN BY	DATE	CHK	SCALE	SIZE
DBLA	11/13/2012	KLN	NONE	A
			SHT 1 OF 1	